


制造工程师问题汇总：

2010-8-19 培训发现：


1、五轴参数线加工的元素不能为裁剪曲面（只能是完整的曲面，中间不能出现断裂或者空）。



2、五轴 G01 钻孔的“直线长度决定钻孔深度”无效，之前的版本可以使用的。




3、3轴转5轴的退刀过切。




此退刀线由实体中间出来。应与进刀角度线一致。

4、五轴等高加工

(1) 生成速度超慢



(2) 线框仿真慢到接近死机状态。



(3) 10 行的轨迹竟然有 27.4 M 的代码?!



```
H100 G90 G55 G0 A0 C0 G05.1Q2  
H102 Z200.  
H104 X-4.999 Y-122.891 Z200. A-40. C-0.012  
H106 S3000 M03  
H108 X-4.999 Y-122.891 Z157.963  
H110 G1 X-4.999 Y-99.942 Z130.613 F1000  
H112 X-4.999 Y-99.942 Z125.613  
H114 X-4.665 Y-101.445 Z124.352  
H116 X-3.592 Y-102.729 Z123.275  
H118 X-1.95 Y-103.59 Z122.552  
H120 X0. Y-103.893 Z122.298  
H122 X0. Y-103.893 Z122.298 C-0.028  
H124 X0. Y-103.892 Z122.299 A-39.999 C-0.043  
H126 X0. Y-103.891 Z122.3 C-0.059  
H128 X0. Y-103.89 Z122.3 C-0.075  
H130 X0. Y-103.89 Z122.301 A-39.998 C-0.09  
H132 X0. Y-103.889 Z122.301 C-0.106  
H134 X0. Y-103.888 Z122.302 C-0.121  
H136 X0. Y-103.887 Z122.303 A-39.997 C-0.137  
H138 X0. Y-103.887 Z122.303 C-0.152  
H140 X0. Y-103.886 Z122.304 C-0.168  
H142 X0. Y-103.885 Z122.305 A-39.996 C-0.183  
H144 X0. Y-103.884 Z122.305 C-0.199  
H146 X0. Y-103.884 Z122.306 C-0.214  
H148 X0. Y-103.883 Z122.306 A-39.995 C-0.23  
H150 X0. Y-103.882 Z122.307 C-0.245  
H152 X0. Y-103.882 Z122.308 C-0.261  
H154 X0. Y-103.881 Z122.308 A-39.994 C-0.277  
H156 X0. Y-103.88 Z122.309 C-0.292  
H158 X0. Y-103.88 Z122.309 C-0.308  
H160 X0. Y-103.879 Z122.31 A-39.993 C-0.323  
H162 X0. Y-103.878 Z122.31 C-0.339  
H164 X0. Y-103.878 Z122.31 C-0.354
```